

Orzo Task Chair

Part # OFC-AC-ORZO XX

20-0331

PARTS




A



B



C



D




x5

E

x2
m6 x 16 mm

F


x2
6 x 25mm

G




H


1




2



3



4



Do not over tighten.
Do not use power tools to assemble.