

Oregon Bar Cart

Part # BTC-OR XX+XX

19-0501

PARTS



A




B


x4
Cx4
Dx20
E

F


1



2



3



4



Do not over tighten.
Do not use power tools to assemble.